

**DEPARTMENT OF TRANSPORTATION**

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch  
690 Walnut Ave.St. 150  
Vallejo, CA 94592-1133  
(707) 649-5453  
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:**Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-015323**Date Inspected:** 29-Jun-2010**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

**CWI Name:** Gao Zhi Chun  
**Inspected CWI report:** Yes No N/A  
**Electrode to specification:** Yes No N/A  
**Qualified Welders:** Yes No N/A  
**Approved Drawings:** Yes No N/A

**CWI Present:** Yes No  
**Rod Oven in Use:** Yes No N/A  
**Weld Procedures Followed:** Yes No N/A  
**Verified Joint Fit-up:** Yes No N/A  
**Approved WPS:** Yes No N/A  
**Delayed / Cancelled:** Yes No N/A

**Bridge No:** 34-0006**Component:** Tower Components**Summary of Items Observed:**

On this date Caltrans Office of Structural Materials Quality Assurance Inspector, Sandeep Kumar (QA) was present during the times noted above for observations relative to the work being performed.

BAY#10

The following Non Destructive Testing (NDT) inspection carried out as per the ZPMC submitted Notification No. 006083

**Visual Inspection Testing (VT)**

This QA inspector performed VT of the area previously tested and accepted by ZPMC Quality Control personnel. The member is identified as Tower Component. The identified component designations reviewed are as follows:

**TOWER SKIRT PLATE**

SSD1 – A434C/D – 1; 2; 3

SSD1 – A434D/D – 60; 61

SSD1 – A434A/D – 16~26

**Magnetic Particle Testing (MT)**

This QA inspector performed MT of the area previously tested and accepted by ZPMC Quality Control personnel.

This QA Inspector generated an MT report for this date. The member is identified as Tower Component. The weld designation reviewed as follows:

---

## WELDING INSPECTION REPORT

( Continued Page 2 of 3 )

---

### TOWER SKIRT PLATE

SSD1 – A434C/D – 1; 2; 3

SSD1 – A434D/D – 60; 61

SSD1 – A434A/D – 21; 22

This QA Inspector observed the following work in progress

Shielded Metal Arc Welding (SMAW):

Weld joint # 3A located on Lift-5 Splice Plate Stiffener SSD1 – SPSA5 – 13. Welder is identified as 052493.

ZPMC Quality Control (QC) Inspector is identified as Yuan Hui Gang. The welding variables recorded by QC appeared to comply with the WPS – B – T – 3211 – Tc – U5b – 1.

Weld joint # 1A located on Lift-5 Splice Plate Stiffener SSD1 – SPSA5 – 1. Welder is identified as 057258.

ZPMC Quality Control (QC) Inspector is identified as Yuan Hui Gang. The welding variables recorded by QC appeared to comply with the WPS – B – T – 3211 – Tc – U5b – 1.

Flux cored Arc Welding (FCAW):

Weld joint # 3 located on Façade Plate SD1 – SFSA3 – 38. Welder is identified as 052075. ZPMC Quality Control (QC) Inspector is identified as Jiang Xiao Bo. The welding variables recorded by QC appeared to comply with the WPS – B – T – 2132.

Weld joint # 9 located on Façade Plate SD1 – SFSA3 – 38. Welder is identified as 052075. ZPMC Quality Control (QC) Inspector is identified as Jiang Xiao Bo. The welding variables recorded by QC appeared to comply with the WPS – B – T – 2132. (See attached photo)

### BAY#11

This QA Inspector observed the following work in progress

Shielded Metal Arc Welding (SMAW):

Weld joint # 4B located on Lift-5 Splice Plate Stiffener ESD1 – SPSA5 – 7. Welder is identified as 046709.

ZPMC Quality Control (QC) Inspector is identified as Li Bin. The welding variables recorded by QC appeared to comply with the WPS – B – T – 3211 – Tc – U5b – 1.

Weld joint # 1A located on Lift-5 Splice Plate Stiffener ESD1 – SPSA5 – 20. Welder is identified as 040611.

ZPMC Quality Control (QC) Inspector is identified as Xu Jie. The welding variables recorded by QC appeared to comply with the WPS – B – T – 3211 – Tc – U5b – 1. (See attached photo)

Weld joint # 13 located on Tower Strut WD1 – STSA4 – 5 – 135M – 1. Welder is identified as 251194. ZPMC Quality Control (QC) Inspector is identified as Liu Dao Feng. The welding variables recorded by QC appeared to comply with the WPS – B – T – 4113 – 1.

Weld joint # 1A located on Lift-5 Splice Plate Stiffener ESD1 – SPSA5 – 12. Welder is identified as 040614.

ZPMC Quality Control (QC) Inspector is identified as Li Bin. The welding variables recorded by QC appeared to comply with the WPS – B – T – 3211 – Tc – U5b – 1.

---

## WELDING INSPECTION REPORT


( Continued Page 3 of 3 )

---

Weld joint # 1A located on Lift-5 Splice Plate Stiffener WSD1 – SPSA5 – 12. Welder is identified as 046704. ZPMC Quality Control (QC) Inspector is identified as Li Bin. The welding variables recorded by QC appeared to comply with the WPS – B – T – 3211 – Tc – U5b – 1.

Weld joint # 37 located on Tower Strut WD1 – STSA4 – 5 – 119M – 1. Welder is identified as 040619. ZPMC Quality Control (QC) Inspector is identified as Liu Dao Feng. The welding variables recorded by QC appeared to comply with the WPS – B – T – 2113.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.



### Summary of Conversations:

No Relevant Conversations.

### Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Michael Ng - 15921845703, who represents the Office of Structural Materials for your project.

---

<b>Inspected By:</b>	Kumar,Sandeep	Quality Assurance Inspector
<b>Reviewed By:</b>	Clifford,William	QA Reviewer

---